

What do you see?



Location: Ethiopia

This Eroded path was stabilized with bushes of Euphorbia Tirucalli.

Fast growing plants that provide good soil cover and have a deep rooting system are preferred because they can stand harsh conditions and be effective quickly.

Photo: Lakew Desta

## 21 - Cattle path stabilization



DWA